

## COMBE MILL SOCIETY

### Safe Method of working with hazardous substances based upon CHIP Safety Data Sheets and COSHH risk assessments

#### 1 **Substance**

Alto 100 Machine oil

#### 2 **Trade Name**

Morris Alto 100 ISO 100 Machine Oil

#### 3 **Main hazards**

- (a) Flammable
- (b) Skin irritation if prolonged skin contact
- (c) Vapour or mist may cause breathing difficulties
- (d) May cause temporary eye irritation

#### 4 **Precautions**

- (a) When transferring from storage drum to oilcan, do so only in a well ventilated area. Take care when removing the oil from the drum and when pouring into an oilcan - keep away from hands and face.  
Avoid breathing fumes. Do not smoke and keep way from all forms of ignition.
- (b) Wear overalls
- (c) Wear protective gloves (neoprene) and safety goggles - ensure eye bath is to hand
- (d) Do not allow prolonged skin contact - promptly remove contaminated clothing.

#### 5 **Reactivity**

Avoid all forms of heat and ignition and contact with strong oxidisers.

#### 6 **Environmental**

Substance is not readily bio-degradable.

Do not dispose of down drains or by throwing into river.